



9373-8680 QUEBEC INC.
 1468 Rue Graham-Bell, Boucherville, QC J4B 6H5
 (514) 573-6403
 TPS: 752340117 RT 0001
 TVQ: 1225436491 TQ.0001

INVOICE # 40

Date: 4/3/2020
Page: 1

Bill to		Véhiclé	
Name: Adisor Relu Mark		Make/Model: Porsche 911 Irish Green Project	
Address: 2 Werchester Drive Lonon ,UK W4 1AB		Year: 1971	
Phone:		VIN: 9111121915	
Email:		Mileage: 0	
		Color: Irish Green	

Description	\$
1971 911 Irish Green , Total rebuilt Motor, gearbox , brakes,suspension,wheels,tiers	
1 carrera chain tensioner update	1,827.56 \$
1 oil line	118.74 \$
1 intermediat shaft B	110.02 \$
1 intermediat seal	27.27\$
1 oil filter	18.00\$
4 oil return tubs 35.21\$	140.84\$
2 timing chain 138.85\$	277.70\$
1 timing guide rail	17.71\$
5 timing railies 28.61\$	143.05\$
12 valve guides 14.65\$	175.80\$
12 rocker shat nuts 8.59\$	103.08\$
24 rocker shat O ring 4.95\$	118.80\$
1 engine gasket set	486.11\$
1 main bearing set	336.67\$
6 piston ring set 35.57\$	213.42\$
12 rocker shaft bolts 10.20\$	122.40\$
1 rod bearing set	200.46\$
12 valve spring set 63.97\$	767.64\$
6 wrist pin bushing 29.32\$	175.92\$
2 rebuil axels	350.00\$
1 rebuilt altarnator	185.00\$
1 oil pressure sender	45.15\$
1 ignition wire set	323.26\$
1 drive bely	7.66\$

	Subtotal:	
	HST/GST/TPS	\$ -

Remarques	TOTAL:
Client signature:	
9373-8680 QUEBEC INC. :	



9373-8680 QUEBEC INC.
 1468 Rue Graham-Bell, Boucherville, QC J4B 6H5
 (514) 573-6403
 TPS: 752340117 RT 0001
 TVQ: 1225436491 TQ.0001

INVOICE # 40

Date: 4/3/2020
Page: 1

Bill to		Véhicule	
Name: Adisor Relu Mark	Make/Model: Porsche 911 Irish Green Project	Year: 1971	
Address: 2 Werchester Drive Lonon ,UK W4 1AB	VIN: 9111121915	Mileage: 0	
Phone:	Color: Irish Green		
Email:			

Description	\$
1971 911 irish Green , Total rebuilt Motor, gearbox , brakes,suspension,wheels,tiers	
page 2 Transmission rebuilt, clutch, Many parts have been provided by client	
1 1st synchro teeth	318.86\$
1 1st synchro ring	180.00\$
1 synchro sleeve	470.00\$
1 clutch kit Sachs , disc ,pressure plate	970.00\$
4 mags repair, resurface,balance 250.00\$	1000.00\$
6 exhaust nuts 7.50\$	45.00\$
6 exhaust washer 1.00	6.00\$
2 heater hose 25,46 \$	50.92\$
1 lower heater hose 79.78\$	159.56 \$
2 mufl	50.00\$
1 rear muffler Dansk	1001.57\$
2 CV joints gasket 17.34 \$	34.68.00\$
1 ground cable	19.59.00\$
1 battry tie down	19.59\$
1 H-6 battry	227.00\$
6 sprk plugs 4.25\$	25.50 \$
total labour 13.505.12 plus 14,10.00\$ for gearbox rebuilt,	14915.00\$
175.6 hours of labour , 110\$ per hour for mecahanical minus discount + 85.00\$ per hour.	
cylinder headmachine shop 175.00\$ times 6	10.50.00\$
parts 10,244.96\$	10,244.96\$
machine shop cylinder honing	180.00\$
connecting rod bearinf brushing instalton 30.00 times 6	180.00\$
there is no HST/GST/TPS , Export car	\$ -

	Subtotal: 26,569.96\$
	HST/GST/TPS \$ -

Remarques	TOTAL: 26569.96\$
Client signature:	
9373-8680 QUEBEC INC. :	

